

NY Thermal Recalls Boilers Due to Carbon Monoxide Hazard

 English



Recalled Trinity Tft gas boiler

Name of product:

NY Thermal (NTI) Trinity Tft and Slant/Fin CHS residential and commercial boilers

Hazard:

The grommet seal can reduce in size over time and dislodge during use and allow the boiler to emit carbon monoxide, posing a CO poisoning hazard.

Remedy:

Repair

Recall date:

15, 2018

Units:

About 16,000 (in addition, about 7,000 were sold in Canada)



Consumer Contact:

NY Thermal at 800-688-2575 from 7 a.m. to 4 p.m. ET Monday through Friday or online at www.NTIboiler.com and click on "Urgent Recall Advisory" at the top of the page for more information.

Recall Details

In Conjunction With:



Description:

This recall involves NY Thermal (NTI) manufactured gas boilers sold under the Trinity Tft and Slant/Fin CHS brand names used for residential and commercial use. The Trinity Tft models have the name "NTI" printed on the front and were sold in metallic-grey. The Trinity Tft60 through Tft250 model boilers measure 33 inches tall by 20 inches wide. The Trinity Tft300 through Tft399 model boilers measure 36 inches tall and 25 inches wide.

The Slant/Fin CHS models have the name "Slant/Fin" and "CHS" printed across the front bottom and were sold in white. The Slant/Fin CHS-85 through CHS-250 model boilers measure 33 inches tall by 20 inches wide. The Slant/Fin CHS-300 through CHS-399 model boilers measure 36 inches tall and 25 inches wide.

The model and UPC numbers are printed on the nameplate located on the right side of the boiler. The following model and UPC numbers are included in this recall:

Brand Name	Model	UPC
Trinity Tft	Tft60	628233731005
Trinity Tft	Tft85	628233731036
Trinity Tft	Tft110	628233731067
Trinity Tft	Tft155	628233731098
Trinity Tft	Tft175	628233731128
Trinity Tft	Tft200	628233731159
Trinity Tft	Tft250	628233731180
Trinity Tft	Tft300	628233731210
Trinity Tft	Tft340	628233733467
Trinity Tft	Tft399	628233731241
Slant/Fin CHS	CHS-85	42541025395
Slant/Fin CHS	CHS-110	42541025401
Slant/Fin CHS	CHS-155	Not available
Slant/Fin CHS	CHS-175	42541025463
Slant/Fin CHS	CHS-200	42541025470
Slant/Fin CHS	CHS-250	42541025487
Slant/Fin CHS	CHS-300	Not available
Slant/Fin CHS	CHS-340	Not available
Slant/Fin CHS	CHS-399	42541025500

Remedy:

Consumers with recalled boilers should immediately contact the installer or distributor of the boiler to schedule a free repair. Consumers who continue use of the boilers while awaiting repair, should have a working carbon monoxide alarm outside of sleeping areas and on every level of the home.

Incidents/Injuries:

The firm has received three reports of the grommet seal deteriorating or becoming dislodged and the boiler leaking condensation and carbon monoxide. No injuries have been reported.

Sold At:

NTI professional wholesalers, heating and plumbing contractors and home appliance wholesalers nationwide from October 2011 through January 2018 for between \$5,000 and \$14,000.

Manufacturer(s):

NY Thermal Inc., of Canada

Importer(s):

NY Thermal Inc., of Canada

Manufactured In:

Canada

Recall number:

18-157

[Report an Incident Involving this Product](#)



This recall was conducted, voluntarily by the company, under CPSC's Fast Track Recall process. Fast Track recalls are initiated by firms, who commit to work with CPSC to quickly announce the recall and remedy to protect consumers.